

HCSD Alterations and Additions Project

6/19/2014

OES Kitchen Addition



Backfilling at Addition



Insulated Concrete Walls



Formed and Poured Walls Complete



Pouring Loading Dock Concrete

HCSD Alterations and Additions Project

6/19/2014


OES Kitchen Renovations



Pouring Concrete Floor in Kitchen



Floor Covered with Coated Burlap for Curing



Masonry and Metal Stud Wall Construction

HCSD Alterations and Additions Project

6/19/2014

OES Classroom Renovations (2nd Sequence)



Classroom Abatement – Code-Compliant Barriers and Negative Air in Place



Floor Tiles Removed



Ceiling Bulkhead Construction



Installing Wiring for Ceiling Lights



Ceiling Installation

HCSD Alterations and Additions Project

6/19/2014

OES Playground Restoration



Removing Existing Walkways



Removing Existing Walkways



Playground Swings Removed

HCSD Alterations and Additions Project

6/19/2014

HS Athletic Field House Restroom Facility Construction



Field House Footer Preparation



Insulated Concrete Forms being Erected



Pouring Concrete Walls

HCSD Alterations and Additions Project

6/19/2014

HS Athletic Field Slit Drainage



Trenching Field for Slit Drains



Slit Drains in Place



Backfilling and Grooming Sand